Universal Hydraulic Bucket Thumb



PowerBrute

Best Hydraulic Universal Thumb

FITS ALL SIZES OF LOADER / BACKHOES AND EXCAVATORS

Separate main
pin makes
bucket change a
breeze. Works
great with all
Buckets &
Quick Couplers.

Full length base plate includes mount stop and remote main hinge pin. <u>Easy installation</u>



6442 W Boekel Rd. • Rathdrum, ID 83858 Toll Free 800-526-8538

Visit Our Internet Web Site at amulet.com

Sold and serviced by:

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE. FOR MODEL, PRICE & SPECIFICATIONS PLEASE CONTACT AMULET OR YOUR NEAREST DEALER.



Best Hydraulic Universal Thumb

Today's competitive market forces you to adapt your work style and equipment to meet tomorrow's jobs. Your backhoe or excavator must also evolve: a bucket on this job, a breaker on the next. The Amulet **PowerBrute** simplifies changing these tools, while giving you the versatility of a hydraulic thumb.

FEATURES

 Remote main-pin means it works great with all Buckets & Quick Couplers, makes changing buckets & other attachments a breeze...
 no need to remove thumb!


 Thumb can be curled independent of bucket (demolition, rock placement, land clearing, etc).

 When not in use the PowerBrute is hydraulically stored tight against dipper stick.

EASY INSTALLATION!



Amulet Offers Seven Different Models in the PowerBrute series. Each model is designed to cover a specific segment of machines that range between 2,500 - 100,000 lbs.. Contact the factory for specific PowerBrute models and specifications (see below) toll free at 1-800-526-8538. Your dealer can quote the model best suited for your particular loader/backhoe, mini or full size excavator.







Full length base plate on most models includes mount stop and remote main hinge pin. <u>Easy installation</u>

• HEAVY DUTY •

- Made with high strength alloy which maximizes performance and minimizes extra weight to dipper stick.
 - Open back design offers improved visibility.
 - Large diameter hardened pins and bushings throughout.
 - Grease zerks on main pin and hydraulic cylinder.

